

Subject: Revised Piston/Drive Blade & Gate Plate
Model 2000 F

Models: 2000 F Trigger Pull Floor Nailer

New Revised Model: 2000F Piston/Drive Blade, & Gate Plate

The revised drive blade has a higher rib which fits into a deeper slot in the gate plate and must be changed as a set. The new revised parts are designed to strengthen the performance of the drive blade.

The original part numbers will no longer be available:

09-20F-8013A Piston/Drive Blade Assembly

09-20F-8046 Gate Plate

The Following New Parts are available individually and as a kit.

Piston/Drive Blade Assembly (thick rib)	Item # 13A	P/N 09-20F-8013R1
Gate Plate (deep slot)	Item # 46	P/N 09-20F-8046R1
Piston/Drive Blade Assembly with Gate Plate (Kit)	Items # 13A and # 46	P/N 09-20F-8013L1

Note: When replacing the original style parts, the new kit must be ordered since the original parts are no longer available and replaced as a set. Individual parts can be ordered after the nailer has been revised.

Original Parts

Revised Parts

