

Subject: Revised Piston/Drive Blade & Gate Plate
Model 2000

Models: 2000 Floor Nailer

New Revised Model 2000 Piston/Drive Blade, & Gate Plate

The new drive blade has a thinner rib which fits into a thinner slot in the gate plate and must be changed as a set. The new revised parts are designed to work more efficiently with the Powernail 20g HD 1" & 1-1/4" cleats.

The old part numbers will no longer be available:

09-20FN-2018 Piston/Drive Blade Assembly (wide rib)

09-20FN-2072 Gate Plate (wide slot)

The Following New Parts will be available individually or as a kit.

Piston/Drive Blade Assembly (thin rib)	Item # 18	P/N 09-20FN-2018R1
Gate Plate (thin slot)	Item # 72	P/N 09-20FN-2072R1
Piston/Drive Blade Assembly with Gate Plate (Kit)		P/N 09-20FN-2018L

Note: When replacing any of the old style parts, the new kit must be ordered since the old parts will no longer be available. Individual parts can be ordered after the nailer has been revised.

